# **The Historic Environment Consultancy**




# CONSERVATION OF BUILDINGS RESEARCH ANALYSIS

48 Amwell St, Islington, London, EC1R 1XS

Planning Ref P072699 Listed Building Consent Ref P072723 Appeal Ref No App/V5570/E/08/2065168/WF Appeal Ref No App/V5570/E/08/2065165/WF othettistoric

Dr Peter Wardle 4/04/2008



New River Design Guide Definition of the Character of the Conservation 6.1 Area 25 6.2 The Character of the Conservation Area......25 6.3 6.4 6.5 Post Georgian Contributions to the Character of The Conservation Area...32 6.6 6.6.1 6.6.2 Myddleton Square ..... .36 New River Head Detractors from The Character of the Conservation Area...... 6.7 7. THE EXISTING BUILDING..... 39 7.1 Abridged Listed Building Description ..... 39 7.2 Description Of Building ..... 40 7.3 West Elevation Front Elevation ..... The Rear (East Elevation) ..... 7.4 75 The Rear Extensions ..... X.... 7.6 Basement ..... Ground Floor. 7.7 7.8 First Floor ..... 7.9 Second Floor. Importance of Building & Contribution to the Conservation Area .......53 7.10 The Condition of the Building......54 8. Buildings At Risk, Monuments and Buildings capable of Beneficial Use .....54 8.1 9. 10. 1 11.1 Loss of basement commercial space. It is essential that the 11.2 Basement front light well distances the shop front from the street. None Basement front light well distances the shop front from the street. None of this 11.3 3. Internal alterations to basement are fundamentally unacceptable -loss 11.4 4. Full width rear extension with roof terrace is considered excessive. .66

11	5 5.	Alteration	of	first	floor	sash	to	door	unacceptable	• -	loss	of	historic
fal	oric and	d design	• • • • •		•••••	•••••	• • • •	• • • • • • •		•••	•••••	• • • •	67
12.	Concl	usions											69


The Historic Environment Consultancy 2008

#### Table of Figures

Figure 1: The Front Elevation as existing Scale 1:100 Figure 2: General Location Plan Figure 3: The Extent of the Conservation Area Figure 4: Phased plan showing the development of the New River co	
Figure 5: Plan of New River Head area, 1741 Figure 6: Modern plan of the New River and Lloyd Baker estates Figure 7: Architects section for the refurbishment of Claremont Squa Figure 8: Distribution of roof gardens and similar Figure 9:Phased plan, 48 Amwell Street @ 1:100 Figure 10: The Distribution of Current Light well Arrangements of Amwell Street. Scale 1:500	
consulta	ancy
Figure 9:Phased plan, 48 Amwell Street @ 1:100 Figure 10: The Distribution of Current Light well Arrangements of Amwell Street. Scale 1:500	
otheths	

#### Table of Plates

	Table of Flates
	Plate1 Shops with Light wells in Amwell St7
	Plate 2 Roof Garden Claremont Square23
	Plate 3 Amwell Street and the junction with River St
	Plate 4 Types of Building in Amwell St27
	Plate 5: New River Estate Houses Architectural Features
	Plate 6: Roof Forms
	Plate 7 Terrace Houses of the New River Estate - Amwell St
	Plate8 Detached House in Neo-classical style of the LLoyd Baker Estate
	Plate 9: 42 Amwell St - Historic Shop front with retained light well and railings 32
	Plate 10: Wharton Street Roof Garden
	Plate 11: A hedge has been used as a boundary at third floor level Wharton Street
	Plate12: Roof Gardens: Roof Gardens
	Plate13 Roof Gardens
	Plate14 The Front Flevation 42
	Plate 15 Modern C20 Door Arrangement
	Plate15 Modern C20 Door Arrangement
	Plate To The Covered Front Light well
	Plate 17 Original Light well looking North 44
	Plate 10 Light well looking South
	Plate 12: Roof Gardens: Roof Gardens
	Plate20 The real Elevation
	Plate21 Showing the use of plastic and iron rainwater goods
	Plate22 Victorian Rain water goods.47Plate 23 Rear Extensions47Plate24 The Basement49
	Plate 23 Redi Extensions
	Plate25 The Ground Floor Looking to the rear of the property
	Plate25 The Ground Floor Looking to the real of the property
	Plate26 Ground Floor Photographs
	Plate27 Structural Instability rear extension
	Plate28 Structural Instability Rear Extension
	Plate29 Missing Floor boards etc ground floor
	Plate30 Shops with lightwells in Amwell St - Note the use of metal grills in the
	middle shop
	Plate 31 Shop Fronts Light Wells & Railings Amwell St East Side
	Plate 32 13 Amwell St - South Of Application Area
	Plate33 Shop Fronts Light Wells & Railings Amwell St West Side
	Plate34 The First Floor Kitchen Window clearly a none Georgian Form
	Plate35 Doors to Balcony River Street
$\bigcirc$	
C	



- 1. The building is a late Georgian Terraced house (1828) constructed as part of the New River Estate a planned Georgian development. The ground floor was converted into a shop in the Victorian Period. The basement has in the past been used as living accommodation.
- 2. It is emphasised that the basement and ground floor building cannot be used in any event without substantial repairs. In English Heritage terms this building is "at risk"
- 3. The fundamental issue is if it is appropriate for a shop within the New River Conservation area to have an existing light well and railings re-instated. Clearly it is and this is supported by Islington UDP Policy. D31 "The Council wishes to see the preservation, retention and reinstatement of front boundary railings, boundary walls and traditional iron work in conservation areas."
- 4. Over half of the shops and all houses in this part of Amwell Street retain their light well. They are an integral part of the design of the original buildings.



Plate1 Shops with Light wells in Amwell St.

5. The original basement frontage survives sealed beneath a relatively recent concrete slab.



#### Figure 1: The Front Elevation as existing Scale 1:100

6. Re-instatement of the original form can only be considered to be an enhancement and a reduction of the detracting Victorian and Modern shop front arrangement to an elegant Georgian Street Scene. The re-instatement of the light well would allow the basement to be brought into beneficial use.

7. There are difficulties in using the basement as ancillary space to retail premises because the stairs are too narrow.

- 8. The re-instatement of the light well is supported by:
  - a. Islington 2002 UDP
  - b. The Principles of PPG 15
  - c. English Heritage Policy on Buildings at Risk
  - d. English Heritage Policy on Sustaining the Historic Environment

- 9. It is thus an absurdity that conservation policy is being used to stop the saving of a listed building "At Risk" from further decay. Ultimately the other conservation matters are matters of detail about what precisely is the best way to re-order this building.
- 10. The presence of roof gardens is an integral and important characteristic of the New River Conservation Area. Indeed when the New River Estate was refurbished by the local authority in 1975 roof gardens were created in as many places as possible.
- 11.At present there is a detracting full width extension consisting of a lean to structure and an earlier extension which has structural difficulties. Its replacement will be an improvement of the visual appearance. 11. At present there is a detracting full width extension consisting of a lean to

A Conservation of Buildings Research Analysis: 48 Amwell St, Islington, London, EC1R 1XS

In connection with planning application reference number: Planning Ref P072699 Listed Building Consent Ref P072723

t consultancy 200 And Appeal Reference Numbers Appeal Ref No App/V5570/E/08/2065168/WF Appeal Ref No App/V5570/E/08/2065165/WF

bv Dr Peter Wardle 4/April/2008

# 1. PART 1 BACKGROUND INFORMATION

#### 1.1 The Basis of The Report.

This is a document describing and discussing a spects of the historic environment (Conservation Areas, Listed Buildings, Ancient Monuments and archaeological sites) in relation to the development proposal at 48 Amwell St.

This follows the principles set out in: Clark, K., 2001, Informed Conservation, English Heritage, London.

The basic premise of this is that:

- All conservation decisions should be based upon research and information.
- Conservation is about managing change not fossilisation of buildings, land or • landscapes.

Other key methodological documents are: English Heritage: Sustaining the Historic Environment

In particular in the document "Sustaining the Historic Environment" historic "assets" are to be graded as follows:

Critical Constant

Tradeable

#### 2. Introduction

#### 2.1 The Client

This report was commissioned by Paul Woods of ESA planning for the appellant Mr N Koulouras Ltd who is the landowners. This document accompanies and should be read in conjunction with the appeal statements by ESA planning.

#### 2.2 Location

Site Address:	48 Amwell St
Borough:	Islington
County:	London
Post Code	EC1R 1XS

The site is located on the east side of Amwell Street. The general location is shown in the following plans.


#### 2.3 Short Description of the Development


Insertion of railings to the front elevation at the ground floor level, opening up of the front light well, excavation of the rear garden to allow for a rear extension at the basement and ground floor level, replacement of window at the first floor level to the rear elevation with a door to allow access onto the roof of the rear extension, railings to the outside of the proposed rear extension (demolition of the existing rear extension) and the conversion of the basement into a self contained flat.

Modifications to the original proposal have been made following a detailed conservation survey of the building and in order to simplify this appeal.

#### 2.4 Site Visit

othe Historic The site was visited on 17/3/2008 and on subsequent dates.





# 3. Historic Environment Planning History & Background.

#### 3.1 Introduction

Table 1 Historic Environment Designations.

ConstraintDetailsWorld Heritage SiteScheduled Ancient MonumentArea of Archaeological ImportanceMentioned in Local PlanSite of Archaeological Interest (mentioned in theSites and Monuments Record)Sites and Monuments Record NumbersConservation AreaListed BuildingBuilding Mentioned in Local Plan

Yes – New River Conservation Area Yes – Grade II as part of a Terrace Amwell St is mentioned

No

No

No

No

#### 3.2 Archaeological Significance

None

#### 3.3 Listed Buildings.

Many of the nearby buildings are listed - these are detailed in appended.

#### 3.4 Conservation Area

The development area is located within the New River conservation area.

The extent of the conservation area is shown in the following figure.

The Historic



#### Figure 3: The Extent of the Conservation Area

#### 4. Conservation Planning Policy Context

#### 4.1 Planning Policy Guidance 15 – The Historic Environment.

Some of the Provisions and Objectives which are relevant to this appeal are highlighted below:

#### Paragraph 3.8

"Generally the best way of securing the upkeep of historic buildings and areas is to keep them in active use."

#### Paragraph 3.10

"The best use will very often be the use for which the building was originally designed, and the continuation or reinstatement of that use should certainly be the first option when the future of a building is considered"

#### Paragraph3.13

"Many listed buildings can sustain some degree of sensitive alteration or extension to accommodate continuing or new uses."

#### Paragraph 3.15

"Achieving a proper balance between the special interest of a listed building and proposals for alterations or extensions is demanding and should always be based on specialist expertise; but it is rarely impossible, if reasonable flexibility and imagination are shown by all parties involved. Thus, a better solution may be possible if a local planning authority is prepared to apply normal development control policies flexibly."

Section 4 Conservation Areas

Paragraph.5.1

#### "Street Furniture

Even the smallest towns contain a wealth of street furniture of historic or architectural interest, such as pillar boxes, telephone kiosks, drinking fountains, railings, clocks and many others, often of local distinctiveness. The appearance of historic streets can be improved by preserving or reinstating such items where appropriate (see Street Improvements in Historic Areas)."

Section 7. The Upkeep and Repair of Historic Buildings

Annex Guidance on Alterations to Listed Buildings

"Annex C C.6 In general the wholesale reinstatement of lost, destroyed or superseded elements of a building or an interior is not appropriate, although, where a building has largely retained the integrity of its design, the reinstatement of lost or destroyed elements of that design could be considered. In such cases there should always be adequate information confirming the detailed historical authenticity of the work proposed."

#### 4.2 Unitary Development Plan

The following policies of the Islington Unitary Development Plan (2002) were considered relevant, as noted in the planning officer's report, to this application:

D1 (Overall Design) D3 (Site Planning) D4 (Designing in Context) D8 (Boundary Walls, Paving, and Street Furniture) D11 (Alterations and Extensions) D22 (New Development) D25 (Roof Extensions) D28 (Rear Extensions) S16 (Protected Shopping Centres) S18 (Changes of use from Retail) Env17 (Protecting Amenity) The Following UDP policies were cited as conservation reasons for refusal. D1 (Overall Design), D3 (Site Planning), D4 (Designing in Context), D8 (Boundary Walls, Paving, and Street Furniture), D11 (Alterations and Extensions) onmer D11 (Alterations and Extensions), D22 (New Development), D25 (Roof Extensions), D28 (Rear Extensions) In addition the following policies are also considered relevant. **D31** Boundaries The wording of these policies is appended.

4.3 Conservation Area Design Guidelines – A Supplement to the UDP. 2002 Chapter 2 New River Conservation Area

Uthis is appended.

## 5. Historic Background.

#### 5.1 The New River Estate

From the time of the first Queen Elizabeth the area is known to have been agricultural land adjacent to a road which leads from the City of London to Islington Hill, until the current buildings were constructed in 1828. (See appended map regression exercise)

In 1602 Islington hill was selected by Sir Hugh Myddleton as the location for a conduit and reservoir for the "New River Project". This was an ambitious project to construct a new river from Amwell and Chadwell near Ware in Hertfordshire, some 20 miles away, to provide fresh water for the rapidly expanding capital city of London. This involved the digging of a channel 38.75 miles long following the 100' foot contour.

The project was officially opened in 1623 by the current monarch King James I and the water supply is still in use today. The main reservoir, filter beds, and associated building were constructed 200m to the south of 48 Amwell St and are called the "New River Head".

The construction of houses on higher ground in the West End meant that a second, higher, upper reservoir was added in 1708 in what is now Claremont Square 100 m to the North of 48 Amwell St. This was converted into a covered reservoir in 1856.

The New River Company had purchased 40 acres of land following law suits in the 1730s and by the end of the seventeenth century their estate was some 45 acres in total. Amwell Street was the principal North South route through the estate which is bounded by Penton Rd in the North and St John St in the east.


This land was used as agricultural land, principally cattle grazing - cattle were driven from all over the country on the hoof for slaughter and butchering at Smithfield market which is less than a mile from the estate. The River head estate therefore provided the ideal location for drovers to fatten up their beasts immediately before sale.


The New Inn public house was built in the early C18 to cater for the drovers.

By 1800 the conditions at Smithfield were far from satisfactory and the Corporation of London began to consider alternative sites and the New Inn Farm on the estate was considered.

Originally the water from the New River Head was distributed by wooden pipes, made of elm, from the River Head to London itself. The network of wooden pipes radiated out from the reservoirs and thus prevented the building of houses in the area surrounding the river head and thus the area was not developed unlike many arterial roads from the city. They were described as being like "threads of a garment" by William Chadwell Mylne, surveyor of the New River Company. Ordnance Survey

# OS Sitemap™





Historic Environment Consulltany 38 Elvendon Rd Goring on Thames Oxon RG8 0DU, T01491 875584 F01491 875239 E:drpeterwardle@yahoo.co.uk www.historicenvironment.co.uk

19




Figure 6: Modern plan of the New River and Lloyd Baker estates

The manufacture of iron pipes began in the middle of the 17<sup>th</sup> century. The New River Company decided a modernisation was necessary and the elm pipes were replaced. This in turn made the construction of houses around the river head possible in due course. At the beginning of the nineteenth century it was decided that the only solution was to plan where streets would eventually be needed and to replace all the wooden pipes with iron pipes located along the streets.

In 1810 plans were drawn up for the development of the area on the land owned by the New River Company. A list of the streets in the New River Estate is appended.

The development followed a standard form for the Georgian Period in that the land owners sold a lease to a builder who had to construct the buildings to a particular design. The builder then leased the completed buildings on a shorter term lease for a much higher rent.

William Chadwell Mylne drew up the master plan for 600 houses to house 5000 people. He also included shops and public houses as well as a Church and a School. The plan was a regular grid pattern of streets and squares; the streets were wider than normal. Some streets were grander than others. The construction of all the houses was done under the supervision of William Chadwell Mylne to his design. The intention was plain Gothic Design.

At the time the 47 acres of land which were to be built upon were surrounded by buildings already. The area is thus a rare example of a large group of buildings built in a coherent way at the very end of the Georgian Period.

Within sixty years (1880) of the construction of the estate the character of the estate had changed. The universal use of coal as a fuel created a grimy and dirty atmosphere and caused incessant "smogs" (a mixture of fog and smoke) some of which lasted for up to 4 months. Whoever could afford it moved further out from central London to the new suburbs served by the new commuter railways and the underground railways. Thus by this date many houses were in multiple occupation and the houses were old, unfashionable and black from pollution. By 1896 13 of the 47 buildings in Myddleton Square had been converted into apartments. (Tames p135)

By this time a number of ground floors had been converted into shops and the light wells payed over.

In 1904 The New River Company's water assets were taken over by the Metropolitan Water Board but the estate remained in the hands of the Company.

In order to avoid the responsibilities of the rent acts passed after the Great War, houses were frequently allow to deteriorate until the tenants moved out. Often the houses were then converted into business premises and let for a premium rent.

The dilapidation of the estate continued into the twentieth century and the insanitary conditions of part of the estate were the subject of a report on bad housing.

In 1974 the Company sold off many of the houses including No 48 to Islington Council. The architects Andrew Sherlock & Partners were commissioned in 1975 to refurbish the properties:

"And so the big houses of the New Estate, and the even bigger Victorian villas built a generation later, were deserted by their well-heeled occupiers and were divided up into tenements: many of which in due course deteriorated into slums, and remained as such until they were rescued in The 1970s."

Sherlock, H.,

Their idealised design for Claremont Square was to divide the houses into two (tak with a separate entrance for the lower flat at basement level which has a garder at basement level.




Figure 7: Architects section for the refurbishment of Claremont Square

In addition the architects were given a free hand at what they could do above parapet level and they pursued a policy of giving as many people as possible a roof - garden. Unusually the flats were designed so the bedrooms of each flat were immediately above each other. (Sherlock 2006)



#### 5.2 The Lloyd Baker Estate

Land between the present Amwell Street and King's Cross Road, once part of the Knights Hospitallers' 'Commandery Mantells', passed in time to one of James II's 'Seven Bishops', Dr William Lloyd, Bishop of St Asaph's. It formed the dowry of his great-granddaughter Mary, who in 1775 married the Revd William Baker, of Gloucestershire.

From 1819 the old clergyman and their son, Thomas Lloyd Baker, developed two of the steep fields for building, with layout and extraordinarily individual houses designed by father and son John and William Joseph Booth, of the Drapers Company.

The work was attended by fierce disputes with the builders, with neighbouring landowners - the New River Company and Lord Northampton, and with Randell, t consultar owner of the large tile-kilns in 'Black Mary's', the lower field.

The houses were built as:

- 1. Detached Villas
- 2. Pairs of villas
- 3. Short Terraces

in a neo-classical style.

Unusually for London, the estate remained in the family's hands until the death of Miss Olive Lloyd Baker in 1975 when it was worth £2 million. Half the property was put up for sale including much of Granville Square, Wharton and Lloyd Baker Streets (but not Lloyd Square), and acquired in 1978 by Islington Council, which refurbished many properties and again substantially reconstructed Granville Square.

#### 5.3 The Blitz.

It is noted that 9105 of the 9899 houses in the Clerkenwell borough were damaged during the blitz. (Tame p150).

For this reason many upper storeys of the buildings in the conservation area have been rebuilt.

# PART THREE CONSERVATION AREA APPRAISAL

### 6. The Conservation Area - Introduction

The New River Conservation area is defined by the surviving elements of the Late Georgian New River Estate, the Lloyd Baker Estate and other contemporary buildings. It is to be contrasted with the surrounding streets which have a lack of uniformity and far more recent buildings.

As such the essential characteristics are those of Georgian Town planning and the architecture is characterized by proportion and balance; simple mathematical ratios were used to determine the height of a window in relation to its width or the shape of a room as a double cube.

# 6.1 New River Design Guide Definition of the Character of the Conservation Area

The Design Guide for the New River Conservation Area published by Islington Borough Council paragraph 2.4 describes the character of the conservation area as follows:

"The predominant character of the New River Conservation Area is residential, although permission will not be granted for the over intensification of residential use in conversion schemes. There are shopping frontages on, for example, Amwell Street, St John Street, Arlington Way and King's Cross Road which provide local services and are an important contribution to the character of the area. Generally, the Council recognises that often the best use for a building is that which it was designed for and will seek to retain public houses, shops and workshops in appropriate uses which will not diminish their special interest. The removal of individual established uses within the conservation area will not be permitted where they contribute to its character."

#### 6.2 The Character of the Conservation Area

The modern character of the conservation area is defined by the historical evolution described above. In particular that nearly all the historic buildings were constructed at the same time on a slope surrounding the Reservoirs of the New River Company in a particular design to a set master plan.

In essence it is a planned coherent Late Georgian area where some of the buildings have been modified in the Victorian Period. However, many of the buildings are heavily re-built and restored in an imitation of the original style. There are also a few Victorian Buildings and numerous more modern buildings.

The Streets are wide and also straight except Amwell St which followed a preexisting road.

25 Historic Environment Consultancy 38 Elvendon Rd Goring on Thames Oxon RG8 0DU, T01491 875584 F01491 875239 E:drpeterwardle@yahoo.co.uk www.historicenvironment.co.uk

#### 6.3 The Street Scene


The main thoroughfare is Amwell St which is characterised by the range of buildings present including:

- 1. Houses
- 2. Industrial & Other Utilitarian Buildings historic and modern
- 3. Public Houses
- 4. Houses whose ground floors have been converted into shops.
- 5. A school

Many commentators suggest the range of shops present give a village feel to the area. Amwell St is therefore to be contrasted with the other historic streets in the conservation area for its diversity of building types and the conversion of houses into shops. (See appended Street Scenes).



Plate 3 movell Street and the junction with River St



#### 6.4 Architectural Styles & Dates of Buildings Present.

It is clear that the character of the conservation area derives from the History of the New River Company and the survival of the buildings constructed by it and the adjoining land owners principally the Lloyd Baker Estate, and its subsequent evolution. Thus the buildings and spaces can be classed as follows:

- 1. The buildings relating to the water based activities of the New River Company
- 2. The houses built by the New River Company in the early C19
- 3. Shops built by the New River Company
- 4. Other Buildings built by the New River Company
- 5. Houses built by the Lloyd Baker Estate in the early C19
- 6. Modern Replacement Buildings
- 7. Modern Garages and other buildings replacing the stabling at the centre of each block.

#### 6.5 Architectural Characteristics & Key Features

The buildings of the New River Company are characterised by the following features:

- 1. Built of brick from brick earth extracted from the company's land
- 2. Of 2-3 Storeys usually plus a basement and an attic
- 3. With the provision of a light well to the basement
- 4. The frontage size varies from 15-20 ft wide with the same number of windows thus mixing grander with more modest houses
- 5. Features which followed the Building Acts following the Great Fire including all wooden parts set back 4 inches into the brickwork
- 6. Cast iron balconies
- 7. String courses

Ther

8. Distinctive feature in the form of Semi circular 'eyebrow' panels in the brick work over the first floor window.

The buildings of the Baker estate can be contrasted by their more classical design.

28 Historic Environment Consultany 38 Elvendon Rd Goring on Thames Oxon RG8 0DU, T01491 875584 F01491 875239 E:drpeterwardle@yahoo.co.uk www.historicenvironment.co.uk






Plate 6: Roof Forms





Plate8 Detached House in Neo-classical style of the LLoyd Baker Estate

#### 6.6 Post Georgian Contributions to the Character of The Conservation Area.

#### 6.6.1 Conversion of Ground floor to Shops

Many commentators suggest that the New River conservation area has a village feel particularly with the shops on Amwell St. Many were converted in the Victorian period and retain Victorian Shop historic frontages.

Of particular relevance to this appeal is the treatment given to light wells and the railings surrounding them when the ground floors were converted into shops.



Plate 9: 42 Amwell St - Historic Shop front with retained light well and railings

C

#### 6.6.2 Roof Gardens & Other Amenity Space

An unusual characteristic of the conservation area is the presence of amenity space and roof gardens on flat roofs on the first floors and higher. Flat areas adjoining mansard roofs or extensions have been utilised. There can be no doubt that the degree to which these roof spaces are utilised is a modern phenonmon. This was a deliberate policy of the architects when the New River Estate was refurbished in 1975.There is even one example of a box hedge being used a boundary between two properties on the third floor.





Plate 10: Wharton Street Roy Garden



Plate 11: A hedge has been used as a boundary at third floor level Wharton Street










Figure 8: Distribution of roof gardens and similar Scale - 1:2500

## 6.7 Detractors from The Character of the Conservation Area.

The things which detract from the special character of the conservation area are as follows.

- 1. Recent Utilitarian Buildings & Modern Housing
- 2. Gaps
- 3. Inappropriate signage
- 4. Infilled Light Wells

The infilling of light wells and the removal of surrounding railings jars with the intended regularity of the buildings and street scenes. It is noted that the railings are mentioned in the listing descriptions and local plan policy protects them and encourages their re-instatement.

It is clear from the historic maps that these started to disappear in the Victorian Period particularly towards the end of streets. It is suggested that in part this is related to the conversion of the properties to business premises in the Victorian era.

# 7. THE EXISTING BUILDING

## 7.1 Abridged Listed Building Description

Below is the listed building description for the building with descriptions of elements not present removed.

"GV II

Twelve terraced houses, 1828-1829.

C19 shop fronts (altered C20) to nos. 44-52 and 66.

Itancy 2008 By William Chadwell Mylne, Surveyor for the New River Estate.

Yellow stock brick set in Flemish bond.

wooden shop fronts to others and stucco dressings; roofs obscured, party-wall brick stacks.

Ground-floor shop and side-hall entrance plan leading to upper floors to nos. 44-52 and 66.

Three storeys with basement; 2 windows each

Other shopfronts extensively altered C20 Gauged-brick flat arches with

predominantly 6/6 sashes to upper floors; 1st floor stucco sill band beneath full-length sashes set in arched brick recesses linked by stucco impost band with individual cast-iron balconies to nos. 54-64 with Vitruvian scroll and anthemion pattern to railings.

Some rebuilding to upper floors. Plain brick parapet with brick string course and stone coping.

The Full listed description is appended.

## 7.2 Description Of Building

The building is a house constructed as part of the New River Estate to Chadwell Mylne's designs in 1828-1829 with a light well to both front and rear. As such it has all the characteristic architectural features of these buildings including:

- 1. Front light well (now covered)
- 2. Rear Light well (now covered)
- 3. Valley roof which is not symmetrical to the building
- 4. Built of brick from brick earth extracted from the company's land
- 5. Usually 3 Storeys plus a basement
- 6. Including all wooden parts set back 4 inches into the brickwork
- 7. Cast iron balconies
- 8. String courses
- 9. Distinctive feature in the form of Semi circular 'eyebrow' panels in the brick work over the first floor window. itan
- 10. Window Shutters
- 11. Sash windows (although few are original)

The building consists of the following elements:

- 1. The original House constructed in 1828-29 to Chadwell Mylne designs
- 2. A Victorian Extension
- 3. Victorian Modifications eg the Shopfront and covering over of the Light well
- 4. Repairs as a result of bomb damage
- other 5. A Modern lean to structure and other modern elements.



## 7.3 West Elevation Front Elevation

The front elevation shows that a modern shop front has been added and the windows are late Victorian (or later) horned sash windows.







#### Plate15 Modern C20 Door Arrangement

The shop front is relatively recent and is not considered worthy of retention (see Conservation Area Design Guide 2.23). When the shop front was added a double door arrangement was constructed in order to allow access to a self contained dwelling on the first and second floors. The light well has been covered by a concrete slab.



#### Plate16 The Covered Front Light well.

The original form of the front elevation is still visible in the basement and consisted of a lightwell and two vaults as well as the original door and window arrangement.



## Plate18 Light well looking South



## 7.4 The Rear (East Elevation)



# Plate20 The rear Elevation

The following architectural features are present

- 1. Both Modern plastic and old cast iron rain water goods are present.
- 2. A mix of horned and unhorned sash windows
- 3. Chimney stack
- 4. Evidence of rebuilding of the adjoining property.
- 5. Evidence of rebuilding of the second floor of the building.
- 6. The addition of a light well to the adjoining property on the left of the photograph.

A number of structural elements can be observed

- 1. The original building at first floor level
- 2. An extension at ground floor level on the right of the photograph
- 3. A lean to structure on the left of the photograph



Plate21 Showing the use of plastic and Plate22 Victorian Rain water goods.

There is some evidence to suggest that the uppermost store has been re-built - the brick work is cleaner and the windows are not original.

7.5 The Rear Extensions



#### **Plate 23 Rear Extensions**

On the left is a recent lean to structure consisting of a make shift roof and the addition of a door. The extension on the right is of Victorian or later date.

## 7.6 Basement

It is unclear what the original internal form of the basement actually was.

The normal arrangement for a Georgian Building of this date would be a single large basement used as a kitchen with pantries and similar.

In broad terms the arrangement was a light well to both front and rear with a door to the front. The form of the rear door suggests that it may be a later addition. It is likely that the central wall may be an original wall.

The stairs to the ground floor lead to an external door and as well as an opening to the ground floor.

Two fireplaces are present - one made of marble and the other fitted with a late cast iron fire surround. Neither are therefore characteristic of a usual basement

48 Historic Environment Consultancy 38 Elvendon Rd Goring on Thames Oxon RG8 0DU, T01491 875584 F01491 875239 E:drpeterwardle@yahoo.co.uk www.historicenvironment.co.uk



## 7.7 Ground Floor.

The Ground Floor retains little of historic interest with the following having been removed:

Windows Front Door Internal walls Skirting boards **Ceiling Rose** Plasterwork Internal wall arrangement

The internal arrangement can be suggested by comparison with other buildings and remnant structural features. It is also possible that the position of the stain case to the first floor was moved from the north to the south walls.



Plate25 The Ground Floor Looking to the rear of the property



## 7.8 First Floor

The first floor retains its original room lay out but virtually no original features remain except:

- 1. Shutters to front windows
- 2. Skirting board to part of the front room.
- 3. Chimney Breast

The rear bedroom has been converted to a kitchen

#### 7.9 Second Floor.

7.9 Second Floor. The second floor retains its original room lay out but no original features remain.

## 7.10 Importance of Building & Contribution to the Conservation Area

Clearly the late Georgian buildings of the New River Estate are of considerable architectural and historic interest both individually and collectively. There can be no doubt that the building as a whole makes a positive contribution to the conservation area.

The importance of the group of buildings is lessened by the following:

- 1. The degree of alteration of the upper storeys
- 2. The high degree of internal alteration.

. the ...ing. ...ing...ing. ...ing. .. The importance of 48 Amwell St is diminished and indeed detracts from the special character of the conservation area by the presence of the following: 1. The presence of a C20 shop front

# 8. The Condition of the Building

It is emphasised that the basement and ground floor building cannot be used in any event without substantial repairs. Some of these repairs will require listed building consent in any event.

In summary the following repairs are necessary before the ground floor and basement can be used for any purposes.

- 1. Upper Floors
  - a. Stop ingress of water on top floor.
- 2. Ground Floor:
- 3. Basement

# 8.1 Buildings At Risk, Monuments and Buildings capable of Beneficial Use

Additional action to wall finishes Memedial action to wall finishes Memedial action to wall finishes Memedial action to wall finishes Memodial action to wall finishes Memo In 1998 English Heritage launched a new strategy for dealing with Listed Buildings which were at Risk in "Buildings at Risk - A new Strategy". This document sets out how the degree of risk that a building is subject to can be analysed. In every case a "vacant" building is the high risk category for each condition stage.

## **English Heritage Definitions of Condition**

English Heritage in "Buildings at Risk - A new Strategy define the following categories of condition. The following table compares the current situation at 48 Amwell St:

	Criterion	Current Situation
	structural failure or instability (where	Some structural instability to the
(C	applicable)	rear extension.
C	a loss of significant areas of roof covering -	In part of extension
	leading to major deterioration of the	No
	interior	
	or where there has been a major fire or	No
	other disaster affecting most of the	No
	building.	

Very Bad means a building where there has been:

Poor means a building or structure with

deteriorating masonry	Yes
and/or leaking roof	Yes
and/or defective rainwater goods,	Yes
accompanied by rot outbreaks within the building	Yes
General deterioration of most elements of	5
the building fabric	basement, to a degree on the 1 <sup>st</sup> and 2 <sup>nd</sup> floors
including external joinery	Yes

Fair means	00
Structurally Sound	No
Minor Repairs required	Yes
Shows signs of a lack of general maintenance	Yes
Good means	
Structurally Sound	No
Weathertight	No
No Significant Repairs Needed	Jlo



Plate27 Structural Instability rear extension



Plate28 Structural Instability Rear Extension



## Plate29 Missing Floor boards etc ground floor

Thus the condition of the building is therefore at best poor decaying into very bad and has clearly gone beyond the fair stage.

The following chart shows how the different risk categories are defined.

## English Heritage Risk Scale

occupied manifestantiset المنظم المعالية المنظم المعالية المنظم المعالية المعالية المعالية المعالية المعالية ال Good - المعالية المعال			RISK CATEGORY
Form PARTIALLY OCCUPIED CONTRACTOR NOTATION AND ADDRESS AND ADDRE			BUILDINGS AT RISK
COCUPIED on antitation of a contraction	VERY BAD Mindra March 1 - Seguration	An and A CANT AND A CANT AND A CANTER AND A	EXTREME RISK
POOR and the feature of the second and the second a	÷.	PARTIALLY OCCUPIED CONTRACTOR AND	GRAVE RISK
FAIR TAILEY OCCUPIED INTERNALLY OCCUPIED INTERNAL AND AND AND AND AT RISK FROM NEAL		OCCUPIED IN THIS IS THE AND	ATRISK
FAIR 1010 TO 101	POOR as a marge and a		
FAIR 1010 TO 101	1.00	And A CONTRACT AND A	
FAIR To the The rest of the rest of VACANT - HEREPORT And DESCRIPTION AND TRANSPORTANCE AND TRANSPORTA	in and a state of the state of	N	VULNERABLE BUILDINGS
BUILDINGS NOT AT RISK FROM NEQLI C		CCCUPIED 4	
BUILDINGS NOT AT RISK FROM NEGLI OCCUPIED International Control of A C	FAIR to the stage of the	VACANT - HE STATISTICS CONTRACTOR CONTRACTOR	
occupied שאמיני איז איז איז איז איז איז איז איז איז אי		PARTIALLY OCCUPIED	
GOOD - En vacant manter manter fallisais steve varenar avriatarat	-		BUILDINGS NOT AT RISK FROM NEGLECT
		OCCUPIED and the analysis of a second s	
PARTIALLY OCCUPIED	GOOD	and the second	
		PARTIALLY OCCUPIED	

As the building is only partially occupied the building, in English Heritage terms, is at best vulnerable or at risk and certainly is becoming at risk. The building is therefore at Risk. English Heritage also suggest that the rate of decay must be considered. In this case there is a real risk if rapid decay and in particular vandalism occurs.

It is noted that the purpose of the designation system is to protect buildings of special historic and architectural interest in the long term, not to create museums consisting of buildings where no change is made.

# 9. Use of the Building & Re-ordering

The building was constructed as a house.

The function of the building as a laundrette has ceased and it is clear that this function could not continue because of the condition of the floor without major repairs. Formally the planning function of the ground floor is a retail function with the use being something normally located with other shops.

There are no good conservation reasons why any functions other than the historic ones are necessary for the long term survival of the building ie as a dwelling or dwelling and shop.

The basement is clearly a domestic arrangement given the presence of fire places and it is noted that these are bedroom rather than kitchen in character which is unusual for a building of this period.

The staircase from the ground floor to the basement is steep and narrow which precludes a retail use even as a store room. This inevitably means that there is a risk that the basement will not be used which is not regarded as beneficial.

Similarly the lack of daylight and the stairs make the basement of limited use within a dwelling.

It is therefore suggested that the basement cannot be beneficially used for either a retail or domestic function without a re-ordering of the property.

A key requirement to bring the basement into use is the provision of daylight and in fact a return to the original arrangement and the re-instatement of the light well and a separate entrance which are in fact key elements in the character of the New River Conservation Area and in particular the houses of the New River Estate.

,The Hist

# **10.** Amended Proposals

It is noted in the main appeal statement that the proposals have been amended because:

- 1. To simplify this appeal.
- 2. Following detailed study of the building and inspection of the basement following the removal of plant associated with the laundrette.
- 3. To clarify what exactly will be retained

Nevertheless comment is made on these matters in the following section.

## 11. Conservation Reasons for Refusal

The views and the reasons for refusal of the conservation officer are reported the Officers Report and are:

*"1. Loss of basement commercial space. It is essential that the shops/businesses on Amwell Street have adequate ancillary space. 2. Basement front light well distances the shopfront from the street. None of this row of shops have front railings or areas. 2. Internal alterations to becoment are fundamentally unseentable loss.* 

3. Internal alterations to basement are fundamentally unacceptable -loss of plan form and loss of fabric, including chimney stack.

*4. Full width rear extension with roof terrace is considered excessive. 5. Alteration of first floor sash to door unacceptable - loss of historic fabric and design.* 

11.1 Loss of basement commercial space. It is essential that the shops/businesses on Amwell Street have adequate ancillary space.

There are difficulties in using the basement as ancillary space to retail premises because the stairs are too narrow.

I am unclear why there is a conservation objection on this basis. Clearly regard has to be given to the viability of a building but in fact the character of the basement is domestic not commercial. As noted above the stairs in effect preclude the use of the basement for commercial purposes without re-ordering.

# 11.2 Basement front light well distances the shop front from the street. None of this row of shops have front railings or areas.

Virtually all the buildings of the New River Estate retain their light wells and surrounding railings - the exception being some shops. The origin of the shops in the Victorian period has been discussed in the history of the conservation area and in particular the removal of railings by 1871. The form of the arrangements of light wells which are present today can be summarised as follows

Arrangement	Number	Percentage
With Railings and Light wells present	10	32%
Light wells present with no railings	7	23%
Permanent cover to Light wells.	14	45%

59

Which shops have railings and/or light wells is haphazard - due to the piece meal conversion of individual houses in the Victorian Period.

Clearly the presence of the light wells is a key and attractive characteristic of the New River Estate buildings. The irregularity of the arrangements of light wells in Amwell St jars with the deliberate regularity of these buildings as originally planned.

Of Key Importance is Current Unitary Development Plan policy 29 which is as follows:

"The Council will not normally permit the filling in or covering over of front basement areas, or the widening of front entrance steps, or the construction of dustbin or meter enclosures."

Similarly the Conservation Conservation Area Design Guidelines - A Supplement to the UDP. 2002 Chapter 2 New River Conservation Area section 2.18 repeats this statement.

The Supporting Text States:

"The majority of the properties in the conservation area have front basement areas, protected by cast iron railings, which are important to the character of the area. The filling in or covering over of these areas prejudices light to the basements and spoils the appearance of the front elevation."

In addition Policy D31 states:

"D31 The Council wishes to see the preservation, retention and reinstatement of front boundary railings, boundary walls and traditional iron work in conservation areas."

This statement clearly points to the lack of a light well and railings on a particular building as detracting from the character of the conservation area.

The current application is seeking in effect to remove a relatively recent covering of the light well and to:

Re-instate the railing which accords with policy D31.

2. Reveal the original form of the facade, few of which remain.

Re-instatement of the original form can only be considered to be an enhancement and a reduction of the detracting Modern shop front arrangement and a return to an elegant Georgian Street Scene in both conservation and UDP terms. The reinstatement of the light well would allow the basement to be brought into beneficial use.

I am thus unclear why the officer's report based upon "conservation's" comments did not contain statements to this effect. Instead the following statement was made:

# Basement front light well distances the shop front from the street. None of this row of shops have front railings or areas.

At best the second part of this statement is an over simplification. The first part could be taken to suggest that it would be beneficial to the conservation area to have the light wells removed from the 17 shops that possess them in Amwell St. Therefore this statement goes against what policy 29 is trying to achieve.

In conservation terms it is an absurdity to suggest the light wells should be removed and lessen the usefulness of an original planned Georgian Design of occupied basements.




Plate30 Shops with high twells in Amwell St - Note the use of metal grills in the middle shop

It is also noted that only the florist on the corner makes use of its shop window to display goods.

Table of Shops and Light well Arrangements

Address	Side	Use		Light well	Date
44 Amwell St	East	Florist			Pre 1871
46 Amwell St	East	Curtains	£		Pre 1871
		Interiors			
48 Amwell St	East	Vacant			Pre 1871
50 Amwell St	East	Newsagents			Pre 1871
52 Amwell St	East	Vets			Pre 1871
66 Amwell St	East	Off Licence			Pre 1871
25 Lloyd Baker	West	Deli			1871-1894
St					

61

22 Amountal Ct				
33 Amwell St	West	Clothes		1871-18
35 Amwell St	West	Chemist		Pre 187
53 Amwell St	West	Bookshop		Pre 187
65 Amwell St	West	Lighting Shop		Pre 187
70 Amwell St	East	Hairdresser	Light well grill	
37 Amwell St	West		Light Well & Railing	
72 Amwell St	East	Vacant	Light well & Railings	
31 Amwell St	West	Clocks	Light well & Railings	
41Amwell St	West	Dry Cleaners	Light well & Railings	
61 Amwell St	West	Vacant	Light well & railings	C
13 Amwell St	West		Light well & Railings	
57 Amwell St	West	Vacant Former Post Office	Light well & railings	200
39 Amwell St	West	Vacant	Light well and Railings	•
24 Lloyd Baker	West		Light well covered with metal	
St (corner with			cover	
Awell St)				
59 Amwell St		Antiques	Light well Metal cover	
63 Amwell St	West		Light well metal grill	
47 Amurall Ct	West	Betting Office	Light well & Railings Part	
67 Amwell St	WCSU		Light well a hallings fait	
42 Amwell St	East	Dairy Produce	Light well & Railings	
	East	Dairy Produce	Light well & Railings	



Figure 10: The Distribution of Current Light well Arrangements of Shops Only in An well Street. Scale 1:500

 $\bigcirc$ 





# **11.3 3.** Internal alterations to basement are fundamentally unacceptable -loss of plan form and loss of fabric, including chimney stack.

It is noted that it is not intended and, never was intended, to remove the chimney stack.

Not withstanding the fact that the proposals are amended I am unclear as to why there is such a fundamental objection to the re-ordering of the basement which in its current form is virtually unusable particularly for retail use. The arrangement of the basement is clearly for domestic occupation which is the proposed function.

The plan form of the basement is not the original one given the following factors.

- 1. The covering of the light well to the front and use of the light well as an internal space.
- 2. Covering of the rear light well and the erection of partitions so that the light well area can be used as a toilet.
- 3. Insertion of modern block work to reinforce the floor.
- 4. Insertion of a partition wall to form a corridor.
- 5. Insertion of a door to the external light well
- 6. Insertion of structural strengthening

The proposed re-ordering of the basement utilises much of the original plan form with the re-instatement of the front lightwell.

In order for the basement to be successfully converted the re-introduction of natural day light is important.

The location of a bathroom is dictated by building regulations and the fact that it is the least important room to have natural day light in. The location of the bathroom is therefore ideally located at the centre of the basement.

## 11.4 4. Full width rear extension with roof terrace is considered excessive.

At present there is a full width extension at the rear of the building.

It is noted that a key characteristic of the rear of the buildings is their irregularity in contrast to the order of the frontages.

The replacement of the lean to structure which has a plastic sheet roof will therefore be an enhancement.

It is clear that there are irregular arrangements of abutting structures to the rear of the buildings and this irregularity is characteristic of the conservation area. There are other properties with full width extensions including the adjoining two properties to the south.

66

It is noted that policy 28 of the UDP and para 2.1.8 of the design guide - height of extensions - suggests that full width extensions should be single storey. The context of this policy makes the intent clear - extensions should be to the level of the ground floor plus roof. This is also inferred in the design guide.

## 11.5 5. Alteration of first floor sash to door unacceptable - loss of historic fabric and design.

While this alteration is no longer proposed the following comments are made.

- 1. The window is not an original feature. The presence of horns demonstrates that it is not Georgian in form. Horned sash windows were first introduced in about 1875 and was the usual form until sash windows ceased to be used. ar ean re salconies consulta Many of the windows in the area are horned and it is unlcear if these relate to post war bomb damage replacement or are late Victorian replacements.
  - 2. Doors on upper storeys are common to give access to balconies, roof gardens





Plate35 Doors to Balcony River Street.

## 12. Conclusions

Dr Peter Wa 9/4/2008

It is suggested that the key part of this application, the revealing of a light well, is a major enhancement of the special character of both the building and the conservation and is supported by UDP policy 31.

At a stroke the basement can be brought into beneficial use and the building fully repaired and thus the building will no longer "be at risk".

From a conservation point of view this proposal has much to recommend it.